




Leaflet No. / Notice n° **463796** rev 00



47" 
119cm 

AVF Incorporated. 3187, Cornerstone Drive, Eastvale, CA 91752, USA

2

Top
Haut

Ax4

M4
16mm

Bx4

M5
16mm

Nx4

M8
25mm

Mx4

M6
35mm

Lx4

M6
25mm

Cx4

M6
16mm

Dx4

M8
16mm

Ex4

M5

Fx4

M6

Gx4

Jx4/8

Kx4

M4
25mm

✗

TV

✓

TV

A/K+E
B+E
C/L/M+F
D/N

TV

A/K+E+J
B+E+J
C/L/M+F+J
D/N+J

TV

A/K+E+J+G
B+E+J+G
C/L/M+F+J+G
D/N+J+G

+

3

Concrete
Béton

✓

✗

+

Fx4

M6

Hx4

Ix4

Lubricate screw thread with soap
Lubrifiez le pas de vis avec du savon

3

✗

TV

✓

TV

A/K+E
B+E
C/L/M+F
D/N

TV

A/K+E+J
B+E+J
C/L/M+F+J
D/N+J

TV

A/K+E+J+G
B+E+J+G
C/L/M+F+J+G
D/N+J+G

+

Fx4

M6

Hx4

Lubricate screw thread with soap
Lubrifiez le pas de vis avec du savon

4

i

ii

Click!